


# Example: Gapped Inductor

## Approximations

- (1) - (3) still apply  
 (4) At the air gap all  $\Phi$  stays within  $A_c$   
 - Neglect fringing flux  
 (good approx if  $l_g \ll w \& h$ )



## Faraday's

$$v(t) = n \frac{d\Phi(t)}{dt} = n A_c \frac{dB(t)}{dt}$$

## Ampere's

$$\oint_C \mathbf{H} \cdot d\mathbf{l} = H_c (l_m - l_g) + H_g l_g = n i(t)$$

$$= \frac{B}{\mu} (l_m - l_g) + \frac{B}{\mu_0} l_g = n i(t) \rightarrow B(t) = \frac{n i(t)}{\frac{l_m - l_g}{\mu} + \frac{l_g}{\mu_0}}$$


$l_m \gg l_g$   
 $\downarrow$   
 $l_m - l_g \approx l_m$

$$v(t) = n A_c \frac{d}{dt} \left( \frac{n i(t)}{\frac{l_m}{\mu} + \frac{l_g}{\mu_0}} \right) = \underbrace{\frac{n^2 A_c}{\frac{l_m}{\mu} + \frac{l_g}{\mu_0}}}_{L} \frac{di(t)}{dt}$$

if  $\frac{l_g}{\mu_0} \gg \frac{l_m}{\mu}$

$$L = \frac{n^2 A_c \mu_0}{l_g}$$

# Gapped Inductor Magnetic Circuit



$$\Phi = \frac{Ni}{R_c + R_g}$$
$$v(t) = N \frac{d\Phi}{dt} = N \frac{d}{dt} \left( \frac{Ni}{R_c + R_g} \right)$$

$$v(t) = \frac{N^2}{R_c + R_g} \frac{di(t)}{dt}$$

$$L = \frac{N^2}{R_c + R_g} = \frac{n^2 A_c}{\frac{l_c - l_g}{\mu} + \frac{l_g}{\mu_0}} \approx \frac{n^2 A_c \mu_0}{l_g}$$

# Effect of Air Gap

$$L = \frac{n^2 A_c}{\frac{l_g}{\mu_0} + \frac{l_m}{\mu}} = \frac{n^2 A_c}{R_c + R_g}$$

$$B(t) = \frac{1}{n A_c} \int v dt$$

$$i(t) = \frac{1}{L} \int v dt$$

$$B(t) = \frac{1}{n A_c} L \cdot i(t)$$


$$B_{sat} = \frac{1}{n A_c} \frac{n^2 A_c}{R_c + R_g} I_{sat}$$

$$I_{sat} = B_{sat} \frac{(R_c + R_g)}{n}$$

Adding Air Gap →



- (1) increase  $I_{sat}$  }
- (2) Decrease  $L$  }
- (3) Reduce  $L$ 's dependence on  $n$

But, allows independent setting of each coil  $n$  &  $l_g$



# Transformer Example

Magnetic Circuit:



$$\Phi = \frac{F_1 + F_2}{R_c} \rightarrow \Phi R_c = n_1 i_1(t) + n_2 i_2(t)$$

if  $R_c$  is very small ( $\mu \rightarrow \infty$ )

$$\Phi = n_1 i_1(t) + n_2 i_2(t)$$

ideal XF equation

Faraday's

$$v_1 = n_1 \frac{d\Phi}{dt}$$

$$v_2 = n_2 \frac{d\Phi}{dt}$$

$$\frac{v_1}{n_1} = \frac{v_2}{n_2}$$

# Nonideal Transformer

Let  $\mathcal{R}_c$  be  $> \phi$


$$N_1 = n_1 \frac{d\Phi}{dt} = n_1 \frac{d}{dt} \left( \frac{n_1 i_1(t) + n_2 i_2(t)}{\mathcal{R}_c} \right)$$

$$\mathcal{R}_c = \frac{l_m}{\mu A_c}$$

$$N_1 = \frac{n_1^2}{\mathcal{R}_c} \frac{di_1}{dt} + \frac{n_1 n_2}{\mathcal{R}_c} \frac{di_2}{dt}$$

$$N_1 = \underbrace{\frac{n_1^2 \mu A_c}{l_m}}_{L_m} \frac{d}{dt} \left( \underbrace{i_1(t) + \frac{n_2}{n_1} i_2(t)}_{i_m} \right)$$

$L_m = \frac{n_1^2 \mu A_c}{l_m} \equiv$  "magnetizing Inductance")



XF Saturation:  
 $i_1(t)$  &  $i_2(t)$  do not have any saturation limit  
 $i_m(t) \rightarrow I_{m,sat}$

$$B(t) = \frac{1}{n_1 A_c} \int v_1(t) dt$$

$$i_m = \frac{1}{L_m} \int N_1(t) dt$$

$$B_{sat} = \frac{1}{n A_c} L_m I_{m,sat}$$

$$I_{m,sat} = B_{sat} n A_c \frac{1}{L_m}$$

# DC Copper Loss

$$R_x = \rho \frac{l_w}{A_w}$$

← length of winding  
← Area of winding

↑  
resistivity  
of  
copper

$$l_w = n \cdot \text{MLT}$$

MLT = "mean length per turn"

