


# Single Phase Motor (Simplified)



Assume magnet produces a maximum flux  $\bar{\Phi}_m$

$$\Phi_{coil} = f(\theta_r) \bar{\Phi}_m$$


$$-1 < f(\theta_r) < 1$$

if magnet spins  $\theta_r \Rightarrow \theta_r(t)$

winding induced voltage

$$v_x = N \frac{d\bar{\Phi}_{coil}}{dt}$$

$$v_x = N \bar{\Phi}_m \frac{d}{dt} f(\theta_r)$$



# Electromechanical Conversion

$$N_x = n \bar{\Phi}_m \frac{d}{dt} f(\theta_r)$$

$$\lambda_m = n \bar{\Phi}_m = \text{"flux linkage"}$$

$$N_x = \lambda_m \cos \theta_r \frac{d\theta_r}{dt}$$

Guess  $f(\theta_r) = \sin \theta_r$

$$N_x = \omega_r \lambda_m \cos \theta_r$$

Assume  $\frac{d\theta_r}{dt} = \text{const} = \omega_r$

Look at  $P_a = N_a \cdot i_a$

$$P_a = i_a^2 R_w + i_a L_w \frac{di_a}{dt} + i_a \omega_r \lambda_m \cos \theta_r$$

↓  
conduction  
loss


↓  
reactive  
power

↓  
Mechanical power

↗ torque goes  
to zero  
due to  
 $\cos \theta_r$

$$P_{\text{mech}} = \tau_r \omega_r = i_a \omega_r \lambda_m \cos \theta_r \rightarrow \tau_r = i_a \lambda_m \cos \theta_r$$

# 2-Pole, 2-Phase PMSM



Two-pole, two-phase PMSM  
terminal characteristics in  
stator reference frame

$$\lambda_a(\theta_r) = \lambda_M \sin(\theta_r)$$

$$\lambda_b(\theta_r) = -\lambda_M \cos(\theta_r)$$


$$v_a = ri_a + \frac{d\lambda_a}{dt} = ri_a + L \frac{di_a}{dt} + \lambda_M \omega_r \cos(\theta_r)$$

$$v_b = ri_b + \frac{d\lambda_b}{dt} = ri_b + L \frac{di_b}{dt} + \lambda_M \omega_r \sin(\theta_r)$$

$$\rightarrow T_m = \lambda_M (i_a \cos(\theta_r) + i_b \sin(\theta_r))$$

ex  
set  
 $i_a = I \sin \theta_r$   
 $i_b = I \cos \theta_r$

# 3-Phase, 2-Pole PMSM



$$\lambda_a(\theta_r) = \lambda_m \sin(\theta_r)$$







$$\lambda_b(\theta_r) = \lambda_m \sin\left(\theta_r - \frac{2\pi}{3}\right)$$

$$\lambda_c(\theta_r) = \lambda_m \sin\left(\theta_r - \frac{4\pi}{3}\right)$$

$$T_m = i_a \lambda_m \omega_r \cos(\theta_r) + i_b \lambda_m \omega_r \cos\left(\theta_r - \frac{2\pi}{3}\right) + i_c \lambda_m \omega_r \cos\left(\theta_r - \frac{4\pi}{3}\right)$$


$$T = \frac{3}{2} \lambda_m I$$

# Different Number of Poles



# 3-Phase, P-Pole PMSM

$P = 4$  example



Electrical and mechanical angle

$$\theta_r = \frac{P}{2} \theta_{rm}$$

Electrical and mechanical speed

$$\omega_r = \frac{P}{2} \omega_{rm}$$

Max torque per amp

$$T_m \leq \lambda_m \frac{P}{2} \frac{3}{2} I$$