






## CCM Flyback: Ringing Due to $L_l$



## MOSFET turn off





## Leakage Voltage Stress

---



## Leakage Switching Loss

---